

# Product Change Notification

## H-206.x1x, H-8xx.x1x, H-8xx.xVx, F-206.S

### Change Description

All products mentioned in this note are being discontinued. Any successor is listed below under "Affected Products". All products will be available until the effective date listed in the table below.

### Impact and Reasons

As part of an effort to realign the product portfolio, PI focusses on products that offer best customer experience and highest reliability.

Internal electronics were upgraded and the MDR68 data connector in the previous versions was replaced by an HD D-sub 78 connector. The HD D-sub 78 is a screw-on type connector which ensures a tight and hence safer connection.

In addition, more firmware features are available for the C-887.5xx controller series.

### Recommended Action

Customers who are looking for a replacement should consider the successor in conjunction with a C-887.5xx controller.

### Affected Products

Product number	Change	Effective date	Successor
<b>H-810.D1</b>	Discontinued	30.04.2019	H-810.D2
H-810.D11	Discontinued	30.04.2019	H-810.D2 + C-887.5xx
H-810.D12	Discontinued	31.03.2019	H-810.D2 + C-887.5xx
<b>H-820.D1</b>	Discontinued	31.03.2019	H-820.D2
H-820.D11	Discontinued	31.03.2019	H-820.D2 + C-887.5xx
H-820.D12	Discontinued	31.03.2019	H-820.D2 + C-887.5xx
H-820.D13	Discontinued	31.03.2019	H-820.D2 + C-887.53x
<b>H-840.B2</b>	Discontinued	31.03.2019	H-840.D2I
H-840.D1	Discontinued	30.04.2019	H-840.D2
H-840.D11	Discontinued	30.04.2019	H-840.D2 + C-887.5xx
H-840.D12	Discontinued	31.03.2019	H-840.D2 + C-887.5xx
H-840.D31	Discontinued	31.03.2019	H-840.D2 + C-887.53x

H-840.G1	Discontinued	30.04.2019	H-840.G2
H-840.G11	Discontinued	30.04.2019	H-840.G2 + C-887.5xx
H-840.G12	Discontinued	31.03.2019	H-840.G2 + C-887.5xx
<b>H-850.G1</b>	Discontinued	30.04.2019	H-850.G2
H-850.G11	Discontinued	30.04.2019	H-850.G2 + C-887.5xx
H-850.G12	Discontinued	31.03.2019	H-850.G2 + C-887.5xx
H-850.G31	Discontinued	31.03.2019	H-850.G2 + C-887.53x
H-850.GV	Discontinued	30.04.2019	H-850.G2V
H-850.GV1	Discontinued	30.04.2019	H-850.G2V + C-887.5xx
H-850.GV2	Discontinued	31.03.2019	H-850.G2V + C-887.5xx
H-850.H1	Discontinued	30.04.2019	H-850.H2
H-850.H11	Discontinued	30.04.2019	H-850.H2 + C-887.5xx
H-850.H12	Discontinued	31.03.2019	H-850.H2 + C-887.5xx
H-850.H31	Discontinued	31.03.2019	H-850.H2 + C-887.53x
H-850.HV	Discontinued	30.04.2019	H-850.H2V
H-850.HV1	Discontinued	30.04.2019	H-850.H2V + C-887.5xx
H-850.HV2	Discontinued	31.03.2019	H-850.H2V + C-887.5xx
<b>H-206.F1</b>	Discontinued	30.04.2019	H-206.F2
H-206.F11	Discontinued	30.04.2019	H-206.F2 + C-887.5xx
H-206.F12	Discontinued	31.03.2019	H-206.F2 + C-887.5xx
<b>F-206.S</b>	Discontinued	31.03.2019	H-206.F2